

March 11 2019
St. Andrews Wesley Church Restorations
Week 4



Chancel with flooring removed



footprints of the original church builders



light fixtures from the sanctuary



light fixtures being removed in the sanctuary



plaster moulds being made of the arches



plaster moulds up close



Sanctuary Work week 4



scaffolding in the sanctuary



strength testing the plaster on various types of carbon wrapping to ensure the plaster will not debond