

**March 25 2019**

**St. Andrews Wesley Church Restorations**

**Week 6**

Big changes this week, all of the walls in the back of house (classrooms, nursery, custodians room and the hallways) all have the plaster off the walls. As you can see in the pictures the reddish walls are terracotta. Terracotta is not stable enough to support the structure of the building, note the crumble terracotta in Marnie's room. All terracotta walls will be removed and replaced. We have secured plywood over the south transept window to protect it but this has caused major cracking in the plaster and the concrete. This makes it so clear as to why we needed to leave the sanctuary, the plaster and concrete really was not stable.



Trefoils removed in sanctuary



south transept window boarded up



nursery and custodian room with no wall



More abatement





Marnie's Rm terracotta



hall from elevator to sanctuary



digging out the crypt



crypt, note the terracotta ceiling which supports the Narthex



nursery and custodian room with no walls