

April 15, 2019

St. Andrews Wesley Church Restorations

Week 9

Scaffolding, scaffolding everywhere! I love the little door that is used to access the scaffolding on the lane side. The sanctuary floor is wet to keep the dust down. The dust comes from the concrete because it was never finished and sealed so it creates dust. The scaffolding in both transepts is amazing, they fill each transept in the shape of a square so they can reach every wall. The pictures do not do it justice. Talking to the lead guy on moulding, he told me he is not good at puzzles and doesn't enjoy doing puzzles so the pieces need to be labelled well so there is no guessing. One of the scaffolders told me the whole history of the church, I asked if he went to the church and how he knew about it? He told me he read the history provided by the Heritage people and is fascinated with the building. I invited him to come worship with us when we reopen.



1 Scaffolding on Nelson St.



2 *Pylons used to block a lane on Nelson St. and the sidewalk*



3 *Scaffolding fills the whole transept, looking up at the ceiling.*



4 Stained glass windows hoarded



5 Moulding in the Narthex



6 more moulding



7 scaffolding to the ceiling



8 a lot of material and equipment in the sanctuary



9 little door into scaffolding on exterior of the building