

**April 1, 2019**

## **St. Andrews Wesley Church Restorations**

### **Week 7**

There is so little yard around the church that they have to stack containers with supplies that they will need. The South transept window is completely boarded up and safe. The orange tarps are used to contain the lead from the paint on the plaster as they remove the plaster. North transept under construction. The front of the church now has fencing on it. When you have a chance check out the sign we have on the corner of Burrard and Nelson (mesh sign on the fencing)



stacked containers due to lack of space



hoarding and abatement



front of church



south transept window



north transept