

St. Andrew's Wesley Restorations

Week 15

Scaffolding everywhere. The blue fabric makes the scaffolding harder for vandals to climb. The white fabric creates the dust containment for the removal of the plaster in the south transept.

All the pipes from the facades have been taken down off the walls. The wooden boxes were transported here from Cassavant Organs in Quebec. The pipes will be loaded into the boxes and shipped to be cleaned. Did you know the pipes are made of leaks and are so soft that the large pipes will collapse under their own weight.









