




pictures 1 & 2 - taking the scaffolding out of the bell tower.





Picture 3 - putting the tools needed to secure the steel frame into the workers in the bell tower.



Pictures 4 & 5 - lifting the steel structure off the truck.



Picture 6 they are starting the lift up to the top of the bell tower